

STATE OF INDIANA

ORIGINAL

INDIANA UTILITY REGULATORY COMMISSION

)

IN THE MATTER OF AN ORDER APPROVING ADVISORY COMMITTEE RECOMMENDATIONS PURSUANT TO) **INDIANA CODE CHAPTER 8-1-26.**

APPROVED:

MAY 28 2014

ORDER OF THE COMMISSION

Indiana Code chapter 8-1-26 provides the procedure for the Indiana Utility Regulatory Commission's Pipeline Safety Division ("Division") to find violations of said chapter. Upon review of those findings, the Indiana Underground Plant Protection Advisory Committee ("Advisory Committee") reviews those recommendations and recommends civil penalties in the Case.

The Cases received pursuant to Indiana Code chapter 8-1-26 and ripe for Commission action are attached hereto and collectively referred to as the Advisory Committee Recommendations.

Pursuant to statute, the Advisory Committee has submitted their recommendations to the Commission. The Commission hereby UPHOLDS the findings of violations by the Pipeline Safety Division and APPROVES the recommendations of the Advisory Committee as listed on the attached pages. The Assistant General Counsel to the Division is hereby directed to prepare and send notice to the parties advising them of the determination.

IT IS SO ORDERED.

STEPHAN, MAYS, WEBER AND ZIEGNER CONCUR: WEBER NOT PARTICIPATING IN THOSE MATTERS INVOLVING VECTREN

MAY 28 2014 **APPROVED:**

I hereby certify that the above is a true and correct copy of the Order as approved.

Brenda A. Howe Secretary to the Commission

Case No. Respondent		Other Party	Recommended Penalty	
3675	NIPSCO	Rex Construction	Training	
3681	NIPSCO	Berry-it, Inc.	Training	
3707	NIPSCO	Steve Underground Construction	Training	
3718	NIPSCO	Rothenberger Co., Inc.	Training	
3807	NIPSCO	Cornerstone Construction Inc.	Training	
3823	NIPSCO	H and G Plumbing and Heating	Training	
3825	NIPSCO	Bore-It	Training	
3835	NIPSCO	D and M Excavating Incorp.	Training	
3846	NIPSCO	All Star Construction and Excavating	Training	
3857	NIPSCO	D and M Excavating Incorp.	Training	
3861	NIPSCO	Asplundh Construction	Training	
3866	NIPSCO	NIPSCO	Training	
3868	NIPSCO	Landmark Landscaping	Training	
3909	NIPSCO	Fort Wayne City Utilities	Training	
3928	NIPSCO	Gatlin Plumbing	Training	
3929	NIPSCO	TJ Lambrecht Construction, Inc.	Training	
3957	NIPSCO	B&D Regional Builders LLC	Training	
3987	NIPSCO	Berry-It, Inc.	Training	
4041	NIPSCO	Asplundh Construction	Training	
4053	NIPSCO	Asplundh Construction	Training	

Case No.	Respondent	Other Party	Recommended Penalty
4056	NIPSCO	NIPSCO	Training
4059	NIPSCO	Todd Gross Drainage	Training
4060	Citizens Energy Group	Freeman Grading	Training
4061	NIPSCO	Gordon Engineering	Training
4063	NIPSCO	Gordon Engineering	Training
4096	NIPSCO	KLS Underground Inc.	Training
4101	NIPSCO	JKC Underground	Training
4111	Citizens Gas	Miller Pipeline	Training
4133	NIPSCO	NIPSCO	Training
4179	NIPSCO	John R. Camden Construction Co.	Training
4188	NIPSCO	Rippe Well Service, Inc.	Training
4196	Citizens Energy Group	Miller Pipeline	Training
4270	NIPSCO	Dolph Excavating Septic Service	Training
4319	NIPSCO	All Bore, Inc.	Training
4333	NIPSCO	H and G Underground Utilities LLC	Training
4369	NIPSCO	Elite Utility Contractors	Training
4436	NIPSCO	American Electric Power	Training
4469	NIPSCO	Fort Wayne City Utilities	Training
4533	NIPSCO	Grimmer Construction Co.	Training
4573	NIPSCO	Rob and Sons Construction	Training
4577	NIPSCO	Hammond Water Department	Training
4578	NIPSCO	NIPSCO	Training

Case No.	Respondent	Other Party	Recommended Penalty
4590	NIPSCO	Environmental	Training
		Construction	
4592	NIPSCO	Gatlin Plumbing	Training
5032	Brittney Padget	NIPSCO	Warning Letter
5131	Mr. Plumbing Inc.	NIPSCO	Warning Letter
5169	Woodruff and Sons	NIPSCO	Training
5174	Infrasource Underground	NIPSCO	Second Training
	Construction		
5178	NIPSCO	NIPSCO	Training
5198	D and M Excavating	NIPSCO	Warning Letter
	Incorp.		

3673	Vectren	Reliable Concrete and	Training
		Construction	
3828	Vectren	Town of Fishers	Training
4072	Vectren	Cornerstone Fence Builders	Training
4232	Vectren	Johnson County	Training
4239	Vectren	Cicero Municipal Utilities	Training
4268	Vectren	Dave Price Excavating Incorp.	Training
4312	Vectren	Hi Speed Utility	Warning Letter
4342	Vectren	QC Communications	Training
4463	Vectren	Wilson Water & Sewer Service, Inc.	Training
4481	Vectren	Badger Directional Boring	Warning Letter
4609	Vectren	James Gray	Warning Letter
4789	Vectren	Karrin Perkins	Warning Letter

Case No.	Respondent	Other Party	Recommended Penalty
4861	Vectren	B L Brown Construction and Excavation	Warning Letter
4957	Vectren	Corner Cable Inc.	Warning Letter
4964	S&G Excavating	Vectren	Warning Letter
5014	Plant Brothers Excavating	Vectren	Warning Letter
5017	Kings Trucking and Excavation, Inc.	Vectren	Warning Letter
5081	Whalen Construction Co.	Vectren	Warning Letter
5091	James Goble	Vectren	Warning Letter
5147	Evansville Water & Sewer Utility	Vectren	Warning Letter
5149	Tecton Construction Management	Vectren	Warning Letter
5150	Lebanon Utilities	Vectren	Warning Letter
5158	BMB Inc.	Vectren	Warning Letter
5165	Town of Salem	Vectren	Warning Letter
5181	Case Construction	Vectren	No civil penalty due to completing mandatory training in last 30 days
5186	Country Manor Trailer Park	Vectren	Warning Letter
5196	Indy Earth Works, Inc.	Vectren	Warning Letter
5243	Feutz Contractors Incorp.	Vectren	Warning Letter
5254	Snuffys Plumbing Center Incorp.	Vectren	Warning Letter
5268	Agricon Incorp.	Vectren	Warning Letter
5634	City of Mitchell	Vectren	Warning Letter

Respondent:	Vectren
Other Party:	Reliable Concrete and Construction
Case No.:	3673
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	August 29, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training

Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

APPROVED:

Ben Warren Chairman

Respondent:	NIPSCO
Other Party:	Rex Construction
Case No.:	3675
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	August 24, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Trainine

Special instructions if warning letter:White LiningPotholingContacting811Clearance Zone (Two-Foot Rule)Damaging LinesSelf Repair

Additional Information: Selking abstains

APPROVED:

w

Ben Warren Chairman

Respondent:	NIPSCO
Other Party:	Berry-It, Inc.
Case No.:	3681
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	August 27, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

Ben Warren Chairman

Respondent:	NIPSCO
Other Party:	Steve Underground Construction
Case No.:	3707
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	September 5, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

hla Ben Warren

(initialed)

Ben Warren Chairman - 17 - t

Respondent:	NIPSCO
Other Party:	Rothenberger Company, Inc.
Case No.:	3718
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	September 6, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training		01	•	
Q				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

War

(initialed)

Respondent:	NIPSCO
Other Party:	Cornerstone Construction Inc
Case No.:	3807
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	September 12, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Tronining				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair	C	

Additional Information: Selking abstains

APPROVED:

Ben Warren Chairman

Respondent:	NIPSCO
Other Party:	H and G Plumbing and Heating
	Underground Utilities
Case No.:	3823
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	September 17, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training				
1				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED: (initialed)

Ben Warren Chairman

Respondent:	NIPSCO
Other Party:	Bore-It
Case No.:	3825
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	September 17, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

Wa

(initialed)

Respondent:	Vectren
Other Party:	Town of Fishers
Case No.:	3828
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	September 18, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training

Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

APPROVED:

Wa

(initialed)

Respondent:	NIPSCO
Other Party:	D and M Excavating Incorporated
Case No.:	3835
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	September 18, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED: 4

Ben Warren Chairman

Respondent:	NIPSCO
Other Party:	All Star Construction and Excavating
	Inc.
Case No.:	3846
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	September 19, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training

Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

to Wa

(initialed)

Respondent:	NIPSCO
Other Party:	D and M Excavating Incorporated
Case No.:	3857
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	September 21, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

Ben Warren Chairman

Respondent:	NIPSCO
Other Party:	Asplundh Construction
Case No.:	3861
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	September 22, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

Ben Warren

(initialed)

Respondent:	NIPSCO
Other Party:	NIPSCO
Case No.:	3866
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	September 24, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Troyining				
		-		
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Renair		

Additional Information: Selking abstains

APPROVED: (initialed)

Respondent:	NIPSCO
Other Party:	Landmark Landscaping
Case No.:	3868
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	September 25, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training Special instructions if warning letter: White Lining Potholing Contacting 811 Clearance Zone (Two-Foot Rule) **Damaging Lines** Self Repair

Additional Information: Selking abstains

APPROVED:

Ben Warren

(initialed)

Chairman

Respondent:	NIPSCO
Other Party:	Fort Wayne City Utilities
Case No.:	3909
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	August 17, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

(initialed)

Respondent:	NIPSCO
Other Party:	Gatlin Plumbing
Case No.:	3928
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	August 17, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training.				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

(initialed)

Respondent:	NIPSCO
Other Party:	TJ Lambrecht Construction, Inc.
Case No.:	3929
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	August 28, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

Ben Warren Chairman

Respondent:	NIPSCO
Other Party:	B & D Regional Builders LLC
Case No.:	3957
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	September 15, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training				
/				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair	_	

Additional Information: Selking abstains

APPROVED:

Ben Warren

(initialed)

Chairman

Respondent:	NIPSCO
Other Party:	Berry-It, Inc.
Case No.:	3987
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	October 2, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

/Vaining				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

Ben Warren Chairman

Respondent:	NIPSCO
Other Party:	Asplundh Construction
Case No.:	4041
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	October 17, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Trouning				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

Ben Warren

Ben Warren Chairman

Respondent:	NIPSCO
Other Party:	Asplundh Construction
Case No.:	4053
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	October 24, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Ivoining.				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

Ben Warren

(initialed)

Respondent:	NIPSCO
Other Party:	NIPSCO
Case No.:	4056
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	October 24, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty: Translow

Irauning	· · · · · · · · · · · · · · · · · · ·			
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

(initialed)

Respondent:	NIPSCO
Other Party:	Todd Gross Drainage
Case No.:	4059
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	October 25, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training				
J				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

Ben Warren

(initialed)

Chairman

Respondent:	Citizens Energy Group
Other Party:	Freeman Grading
Case No.:	4060
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	October 25, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Renair		

Additional Information: Warren abstains

APPROVED:

(initialed)

Dan Meiners Vice Chairman

Respondent:	NIPSCO
Other Party:	Gordon Engineering
Case No.:	4061
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	October 25, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training				
)				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair	-	

Additional Information: Selking abstains

APPROVED:

(initialed)

Respondent:	Vectren
Other Party:	Cornerstone Fence Builders
Case No.:	4072
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	October 29, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty: Training

~			
Special instructions if warning letter:	White Lining	Potholing	Contacting 811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair	

Additional Information:

APPROVED:

Ben Warren Chairman

Respondent:NIPSCOOther Party:Gordon EngineeringCase No.:4083Date of Advisory Meeting:February 25, 2014Date of Damage:October 31, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training			•	
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

Ben Warren Chairman

Respondent:	NIPSCO
Other Party:	KLS Underground Inc.
Case No.:	4096
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	November 6, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Renair		

Additional Information: Selking abstains

APPROVED:

(initialed)

Respondent:	NIPSCO
Other Party:	JLC Underground
Case No.:	4101
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	November 8, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

ra	ini	ng	

Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

(initialed)

Respondent:	Citizens Gas
Other Party:	Miller Pipeline
Case No.:	4111
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	November 13, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training	-			
	•			
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Warren abstains

APPROVED:

(initialed)

Dan Meiners Vice Chairman

Respondent:	NIPSCO
Other Party:	NIPSCO
Case No.:	4133
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	September 7, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Trayining			•	
	· · · · ·			
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

Ben Warren Chairman

Respondent:	NIPSCO
Other Party:	John T Camden Construction Company
Case No.:	4179
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	September 13, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Trouinin g

Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED: ____

Wa

(initialed)

Respondent:	NIPSCO
Other Party:	Rippe Well Service Inc.
Case No.:	4188
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	October 9, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training

Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

(initialed)

Respondent:	Citizens Energy Group
Other Party:	Miller Pipeline
Case No.:	4196
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	October 10, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training				
J				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Warren abstains

APPROVED:

(initialed)

Dan Meiners Vice Chairman

Respondent:	Vectren
Other Party:	Johnson County R.E.M.C.
Case No.:	4232
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	November 20, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Tratation

·				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

APPROVED:

Ben Warren Chairman

Respondent:	Vectren
Other Party:	Cicero Municipal Utilities
Case No.:	4239
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	November 26, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

raining				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

APPROVED:

(initialed)

Respondent:	Vectren
Other Party:	Dave Price Excavating Incorporated
Case No.:	4268
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	December 6, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training				
J				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

APPROVED:

1/2

(initialed)

Respondent:	NIPSCO
Other Party:	Dolph Excavating Septic Service
Case No.:	4270
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	December 6, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

(vaininc				
			<u> </u>	
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

In War

(initialed)

Committee Recommendation to IURC

Respondent:	NIPSCO
Other Party:	All Bore, Inc.
Case No.:	4319
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	January 8, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Fame	Training			
J	J			
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

Mar

(initialed)

Respondent:	NIPSCO
Other Party:	H and G Underground Utilities LLC
Case No.:	4333
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	January 17, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

· I raining				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

(initialed)

Respondent:	Vectren
Other Party:	QC Communications
Case No.:	4342
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	January 24, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Special instructions if warning letter:	White Lining	Potholing	Contacting 81	11
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

Training

APPROVED:

Ben Warren Chairman

Respondent:	NIPSCO
Other Party:	Elite Utility Contractors
Case No.:	4369
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	October 22, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

J				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair	:	

Training

Additional Information: Selking abstains

APPROVED:

(initialed)

the air and

Chairman

Ben Warren

Respondent:	NIPSCO
Other Party:	American Electric Power
Case No.:	4436
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	January 3, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty: Tro ininm

Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

(initialed)

Respondent:	Vectren
Other Party:	Wilson Water & Sewer Service, Inc.
Case No.:	4463
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	February 11, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

- raming				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

APPROVED:

Ben Warren Chairman

Respondent:	NIPSCO
Other Party:	Fort Wayne City Utilities
Case No.:	4469
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	February 13, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

Ben Warren Chairman

Respondent:	NIPSCO
Other Party:	Grimmer Construction Company
Case No.:	4533
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	March 1, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		. s

Additional Information: Selking abstains

Training

APPROVED:

(initialed)

Respondent:	NIPSCO
Other Party:	Rob and Sons Construction
Case No.:	4573
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	March 22, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training		U 1	-	
<u> </u>			а 1	
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair	·	

Additional Information: Selking abstains

APPROVED:

(initialed)

Respondent:	NIPSCO
Other Party:	Hammond Water Department
Case No.:	4577
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	March 25, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

~			· · · · · · · · · · · · · · · · · · ·
Special instructions if warning letter:	White Lining	Potholing	Contacting 811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair	

Additional Information: Selking abstains

APPROVED:

Ben Warren Chairman

Respondent:	NIPSCO
Other Party:	NIPSCO
Case No.:	4578
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	March 25, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

.

Additional Information: Selking abstains

Training

APPROVED:

Ben Warren

Respondent:	NIPSCO
Other Party:	Environmental Construction
Case No.:	4590
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	April 1, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

(initialed)

Respondent:	NIPSCO
Other Party:	Gatlin Plumbing
Case No.:	4592
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	April 2, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-18(f) - mislocate or failure to locate

The Advisory Committee recommends the following penalty:

Training

Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

Ben Warren Chairman

Respondent:	Woodruff and Sons
Other Party:	NIPSCO
Case No.:	5169
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	July 19, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-20(a)(1) - failure to plan to minimize damage or interference

The Advisory Committee recommends the following penalty:

Training

Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

& Wa

(initialed)

Respondent:	Infrasource Underground Construction
Other Party:	NIPSCO
Case No.:	5174
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	July 22, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-20(a)(2) - failure to maintain two (2) feet clearance with mechanized equipment

The Advisory Committee recommends the following penalty:

- training c	second)	···· - ·		
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair	Contacting	011

Additional Information: Selking abstains

APPROVED: (initialed)

Respondent:	NIPSCO
Other Party:	NIPSCO
Case No.:	5178
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	July 24, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-20(a)(2) - failure to maintain two (2) feet clearance with mechanized equipment

The Advisory Committee recommends the following penalty:

Training				
J	_			
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

(initialed)

Respondent:	Hi Speed Utility
Other Party:	Vectren
Case No.:	4312
Date of Advisory Meeting:	November 26, 2013
Date of Damage:	January 5, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-20(a)(2) - failure to maintain 2-ft clearance with mechanized equipment

The Advisory Committee recommends the following penalty:

Wa	rning let	ter		
	\mathcal{O}			-
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

APPROVED: (initialed)

Ben Warren Chairman

Respondent:	Badger Directional Boring
Other Party:	Vectren
Case No.:	4481
Date of Advisory Meeting:	November 26, 2013
Date of Damage:	February 21, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-20(a)(2) - failure to maintain 2-ft clearance with mechanized equipment

The Advisory Committee recommends the following penalty: $(1)^{2} \cap (1)^{2} \cap (1)^{2}$

Dam	na letter			
	\int			
Special instructions if warning letter:	White Lining	Potholing	Contacting	Q11
	white Lining	<u>i otnonng</u>	Contacting	011
(Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

APPROVED:

the ha

(initialed)

Respondent:	James Gray
Other Party:	Vectren
Case No.:	4609
Date of Advisory Meeting:	August 27, 2013 Dec 17, 2013
Date of Damage:	April 5, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-16(g) - failure to provide notice of excavation

The Advisory Committee recommends the following penalty:

	()			
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

APPROVED:

Ben Warren Chairman

Respondent:	Karrin Perkins
Other Party:	Vectren
Case No.:	4789
Date of Advisory Meeting:	August 27, 2013 Dec 17, 2013
Date of Damage:	April 27, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-16(g) - failure to provide notice of excavation

The Advisory Committee recommends the following penalty:

(1)ar	nors Selle)		
	σ			
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

APPROVED: (initialed)

Wa

Respondent:	B L Brown Construction and Excavation
Other Party:	Vectren
Case No.:	4861
Date of Advisory Meeting:	November 26, 2013
Date of Damage:	May 24, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-20(a)(1) - failure to plan to minimize damage or interference

The Advisory Committee recommends the following penalty:

Nam	My Gerle)		
-	()			
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Renair		

Additional Information: ______

Inton k

Respondent:	Corner Cable Inc.
Other Party:	Vectren
Case No.:	4957
Date of Advisory Meeting:	November 26, 2013
Date of Damage:	June 20, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-20(a)(2) - failure to maintain 2-ft clearance with mechanized equipment

The Advisory Committee recommends the following penalty:

le Jarner	ng letter	01	•	
	<i>[</i>]			
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

APPROVED:

(initialed)

Respondent:	S&G Excavating
Other Party:	Vectren
Case No.:	4964
Date of Advisory Meeting:	August 27, 2013 Dec 17, 2013
Date of Damage:	June 6,2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-16(g) - failure to provide notice of excavation

The Advisory Committee recommends the following penalty:

Warn	ing Netter			
	7			
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

APPROVED:

(initialed)

- 11/41-1

Respondent:	Plant Brothers Excavating
Other Party:	Vectren
Case No.:	5014
Date of Advisory Meeting:	August 27, 2013 pec 17, 2013
Date of Damage:	June 21,2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-16(g)(expire) - failure to provide notice of excavation (expired ticket)

The Advisory Committee recommends the following penalty:

, Darn	ung Metter			
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

APPROVED: (initialed)

Respondent:	Kings Trucking and Excavation Inc.
Other Party:	Vectren
Case No.:	5017
Date of Advisory Meeting:	November 26, 2013
Date of Damage:	June 24, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-20(a)(2) - failure to maintain 2-ft clearance with mechanized equipment

The Advisory Committee recommends the following penalty:

Warning	a letter		-	
(Г Г			
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: _____

APPROVED: (initialed)

Respondent:	Whalen Construction Company
Other Party:	Vectren
Case No.:	5081
Date of Advisory Meeting:	November 26, 2013
Date of Damage:	July 12, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-20(a)(2) - failure to maintain 2-ft clearance with mechanized equipment

The Advisory Committee recommends the following penalty:

Warning le	te	_		
()				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

APPROVED: _

Ben Warren Chairman

Respondent:	James Goble
Other Party:	Vectren
Case No.:	5091
Date of Advisory Meeting:	August 27, 2013 pec 17, 2013 PC
	July 16, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-16(g) - failure to provide notice of excavation

The Advisory Committee recommends the following penalty: 1 1 april Setter)

	<u>A.100</u>	- <u> </u>		
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

APPROVED:

Ben Warren

Chairman

Respondent:	Feutz Contractors Incorporated
Other Party:	Vectren
Case No.:	5243
Date of Advisory Meeting:	November 26, 2013
Date of Damage:	August 5, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-20(a)(2) - failure to maintain 2-ft clearance with mechanized equipment

The Advisory Committee recommends the following penalty:

Warning	lotter		·	
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

Na. Ĺ

APPROVED: (initialed)

Respondent:	Snuffys Plumbing Center Incorporated
Other Party:	Vectren
Case No.:	5254
Date of Advisory Meeting:	November 26, 2013
Date of Damage:	August 6, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-20(a)(1) - failure to plan to minimize damage or interference

The Advisory Committee recommends the following penalty:

Warnin	ng lotter .	• •	•	
	\mathcal{O}			
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

APPROVED: 🔏

Wa

Ben Warren Chairman

Respondent:	Agricon Incorporated
Other Party:	Vectren
Case No.:	5268
Date of Advisory Meeting:	November 26, 2013
Date of Damage:	August 8, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-20(a)(1) - failure to plan to minimize damage or interference

The Advisory Committee recommends the following penalty:

Warne	ng leller	*		
	01			
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

(initialed)

APPROVED:

Respondent:	City Of Mitchell
Other Party:	Vectren
Case No.:	5634
Date of Advisory Meeting:	August 27, 2013 Dec 17, 2013
Date of Damage:	June 28, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-16(g) - failure to provide notice of excavation

The Advisory Committee recommends the following penalty:

Warningo	Jeffer			
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

APPROVED: (initialed)

Respondent:	Brittney Padget
Other Party:	NIPSCO
Case No.:	5032
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	June 29, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-16(g) - failure to provide notice of excavation

The Advisory Committee recommends the following penalty:

Special instructions if warning letter:	White Lining	Potholing	Contacting 811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair	

Additional Information: Selking abstains

APPROVED:

Ben Warren

(initialed)

Respondent:	Mr. Plumber Inc.
Other Party:	NIPSCO
Case No.:	5131
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	June 24, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-16(g) - failure to provide notice of excavation

The Advisory Committee recommends the following penalty: warning letter

Special instructions if warning letter:	White Lining	Potholing	Contacting 811,
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair	

Additional Information: Selking abstains

APPROVED:

Ben Warren

(initialed)

Chairman

Respondent:	BMB Inc.
Other Party:	Vectren
Case No.:	5158
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	July 5, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-16(g)(expire) - failure to provide notice of excavation (expired ticket)

The Advisory Committee recommends the following penalty:

Warnie	NOL	letter			
Y	• 1	• 14	XX/1 · 4 T · ·	D (I I'	C

Special instructions if warning letter:	White Lining	Potholing	Contacting	<u>811</u>
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

APPROVED:

(initialed)

Respondent:	Town of North Salem
Other Party:	Vectren
Case No.:	5165
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	July 3, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-16(g) - failure to provide notice of excavation

The Advisory Committee recommends the following penalty:

Warning letter _____ Special instructions if warning letter: White Lining Potholing Contacting 811 Clearance Zone (Two-Foot Rule) Damaging Lines Self Repair Availability of emergency locate

Additional Information:

APPROVED:

Ben Warren Chairman

Respondent:	Indy Earth Works, Inc.
Other Party:	Vectren
Case No.:	5196
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	July 18, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-16(g) - failure to provide notice of excavation

The Advisory Committee recommends the following penalty:

\sim			
Special instructions if warning letter:	White Lining	Potholing (Contacting 811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair	

Additional Information:

APPROVED:

Ben Warren Chairman

Respondent:	D and M Excavating Incorporated
Other Party:	NIPSCO
Case No.:	5198
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	July 26, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-16(g)(outside) - failure to provide notice of excavation (outside ticket locate)

The Advisory Committee recommends the following penalty:

Warning It	etter			
J				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: Selking abstains

APPROVED:

Ben Warren

Chairman

Respondent:	Country Manor Trailer Park
Other Party:	Vectren
Case No.:	5186
Date of Advisory Meeting:	February 25, 2014
Date of Damage:	June 7, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-16(g) - failure to provide notice of excavation

The Advisory Committee recommends the following penalty: Warning letter

J			
Special instructions if warning letter:	White Lining	Potholing (Contacting 811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair	

·

Additional Information:

APPROVED:

Ben Warren

(initialed)

seven barel

Chairman

Respondent:	Evansville Water & Sewer Utility
Other Party:	Vectren
Case No.:	5147
Date of Advisory Meeting:	January 21, 2014
Date of Damage:	July 3, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-20(a)(2) - failure to maintain two (2) feet clearance with mechanized equipment

The Advisory Committee recommends the following penalty:

Warnin	g Setter			
(カ			
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: _____

APPROVED:

(initialed)

Respondent:	Tecton Construction Management
Other Party:	Vectren
Case No.:	5149
Date of Advisory Meeting:	January 21, 2014
Date of Damage:	June 10, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-16(g) - failure to provide notice of excavation

The Advisory Committee recommends the following penalty:

Marany Jano				
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information: _____

APPROVED:

(initialed)

Respondent:	Lebanon Utilities
Other Party:	Vectren
Case No.:	5150
Date of Advisory Meeting:	January 21, 2014
Date of Damage:	July 11, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-16(g) - failure to provide notice of excavation

The Advisory Committee recommends the following penalty:

Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

APPROVED: 1

(initialed)

Respondent:	Case Construction
Other Party:	Vectren
Case No.:	5181
Date of Advisory Meeting:	January 21, 2014
Date of Damage:	July 25, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-20(a)(1) - failure to plan to minimize damage or interference

The Advisory Committee recommends the following penalty:

\$ 3,000	+ No Civil Penalt	y due to	Completing	
Mandatsy Training	in lost 30 dai	У Ф.	đ	
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		

Additional Information:

APPROVED: 1 (initialed) Ben Warren

Chairman

Respondent:	TSI Paving
Other Party:	Vectren
Case No.:	5155
Date of Advisory Meeting:	January 21, 2014
Date of Damage:	July 12, 2013

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-20(a)(1) - failure to plan to minimize damage or interference

The Advisory Committee recommends the following penalty:

Additional Information: _____

APPROVED: 1

(initialed) Ben Warren Chairman

Respondent:	Martins, Inc.
Other Party:	NIPSCO
Case No.:	4722
Date of Advisory Meeting:	August 27, 2013 Dec 17, 2013
Date of Damage:	December 17, 2012

The IURC Pipeline Safety Division finds the following violation: IC 8-1-26-16(g) - failure to provide notice of excavation

The Advisory Committee recommends the following penalty:

Clearance Zone (Two-Foot Rule)	Damaging Lines	Self Repair		
Special instructions if warning letter:	White Lining	Potholing	Contacting	811
0,			d	
Training	on #5000 if fo	ul to train	temely	

Additional Information: Selking abstains

APPROVED:

(initialed)